
Plant Service Bulletin

Spray Attemperators for Industrial Boilers



in or near the weld.

Purpose

This plant service bulletin (PSB) advises owners and operators of known superheater attemperator problems and provides recommendations for corrective action.

Background

The first direct-contact spray attemperator on B&W boilers went into service in the mid-1950s. Most of the attemperators were designed and built by B&W, although some were supplied by other manufacturers.

PSB-15 was issued in 1985 to notify customers of problems experienced with B&W spray attemperators. However, attemperators built by other manufacturers also have experienced problems on many industrialsized boilers. This bulletin expands on the information supplied in PSB-15.

Problem

Depending on the operating characteristics of a particular boiler and the extent of load swings it is subjected to, the spray attemperator assembly can experience extensive thermal cycling. Factors contributing to thermal cycling include:

- Temperature differentials between steam and water
- Intermittent (on/off) attemperator operation
- Low-load boiler operation

Of the few attemperator failures reported, the cause was mainly attributed to thermal cycling between steam and spray water temperatures. Problems associated with these failures have included:

- Cracks in or near dissimilar material welds (Figure 1)
- Cracks in the older spray nozzle design (Figures 2 and 3)
- Cracks in the attemperator steam line when a liner is not used

- Cracks in the thermal liners which have caused pieces to break off and be carried into the downstream piping
- Spray nozzles that have broken off and become lodged in the venturi or further in the downstream piping



Figure 2 *Crack in an older* spray nozzle design.





Figure 3 *Nozzle cracks can* occur from extensive thermal cycling between steam and spray water temperatures.

Figure 4 Failed attemperator spray head.



Warning

If small parts of the attemperator system break off and are carried downstream, tube plugging may occur and cause localized tube overheating. Larger parts of the spray head also can break loose (Figure 4) and get lodged in the venturi. If this occurs, steam flow is blocked, causing increased pressure drop and uncontrolled steam temperatures. Steam leakage also can result from cracks that have developed in the attemperator body and propagated through the wall.

Design improvements for life extension

To extend attemperator life, B&W has made the following design improvements:

- 1. A thermal liner was added to the spray attemperator (Figure 5), which protects the high-temperature piping from thermal shock.
- 2. The spray attemperator material was changed to low-alloy steels, eliminating the need for dissimilar metal welds which can crack (reference Figure 1).


- One-piece cast spray nozzle heads were designed to eliminate the need for a welded backplate.
- Purchasing specifications and quality control procedures were made much more stringent.

Inspection recommendations

All attemperators with liners should be visually inspected after 10 years of operation. Those without a liner, however, should be inspected after five years of service (Figure 6). Future inspections for all attemperators should be on five-year intervals unless damage is found.

The visual inspection should thoroughly examine the following areas for damage:

- Spray Nozzle Assembly (Figure 7) – including the diaphragm, welds on the nozzle extensions (weld #1 and #2), backplate, and the inside and outside of the spray head
- Attemperator Liner, if one exists (Figure 8) including the liner welds (circumferential






Figure 6 The Graham attemperator design does not have a liner.

and longitudinal) and the liner retainer block welds

Attemperator Body –
including cracks and erosion,
especially when there is not a
liner (reference Figure 6)

All areas should be inspected for cracked or broken welds and cracked or broken nozzles, liners and piping. Depending on observations made during the initial inspection, a schedule for subsequent inspections can be determined. The preferred


inspection method is to remove the spray nozzle and inspect the venturi and thermal liner using a fiber optic scope or microchip camera. These inspections also can be performed with a fiber optic scope through a radiograph plug or thermowell opening.

The results of the inspection will determine the extent of the repairs. However, if extensive repairs are required, a complete attemperator replacement may be more economical. If a

replacement is needed, the attemperator should incorporate B&W's latest design enhancements, which include changing materials to low-alloy steels and adding a thermal liner.

Support

Contact Field Service
Engineering through your local
B&W district service office to
coordinate your inspection and
repair efforts, and to answer any
questions.







Figure 7 B&W spray nozzle assembly.

Figure 8 Cross section of a typical B&W attemperator assembly.

For more information, or a complete listing of our sales and service offices worldwide, call 1-800-BABCOCK (222-2625) in North America. Outside North America, call (330) 753-4511 or fax (330) 860-1886 (Barberton, Ohio, USA). Or access our Web site at http://www.babcock.com.



Canada:

Cambridge, Ontario Edmonton, Alberta

Halifax (Dartmouth), Nova Scotia

Montreal, Quebec

Saint John, New Brunswick

Vancouver (Richmond), British Columbia

Czech Republic: Prague

Egypt: Cairo England: London India: Pune Indonesia: Jakarta Mexico: Mexico City

People's Republic of China: Beijing

Poland: Warsaw Russia: Moscow Taiwan: Taipei Turkey: Ankara

United States of America:

Atlanta, Georgia Charlotte, North Carolina Cherry Hill, New Jersey Chicago (Downers Grove), Illinois

Cincinnati, Ohio
Denver (Sheridan), Colorado

Houston, Texas Kansas City, Missouri

San Francisco (Vacaville), California

Powering the World Through Teamwork and Innovation[™]

The information contained herein is provided for general information purposes only and is not intended or to be construed as a warranty, an offer, or any representation of contractual or other legal responsibility.

Powering the World Through Teamwork and Innovation is a service mark of The Babcock and Wilcox Company.